

**Info - Tire Rotation on Vehicles with Different Front and Rear  
Tire/Wheel Sizes #05-03-10-015 - (Oct 11, 2005)**

**2004-2006 Cadillac SRX**

**2005-2006 Cadillac STS with V8**

**2006 Cadillac STS-V**

**2003-2006 Chevrolet SSR**

**2005-2006 Chevrolet Corvette**

**2005-2006 Pontiac Grand Prix GXP**

The above listed vehicles are manufactured with tire/wheel assemblies that are different in size from front to rear. In this case, the tires should not be rotated.

If a customer requests to have the tires rotated during normal maintenance, explain to them that the tire/wheel assemblies on their vehicle were designed to be different sizes to enhance the vehicle's handling performance.

**Important:** Changing the tire/wheel sizes or rotating the tires may affect the vehicle's handling and ride characteristics. GM DOES NOT recommend changing the OEM tires or wheels.