

**Owner Manual Supplement**

The heated windshield washer fluid system has been permanently disabled and removed from this vehicle.